

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale
04-Jan	Passenger Traction	Phone and alarm bell not working/escape hatch not secure
04-Jan	Roped Hydro	Low Pressure switch not working
04-Jan	Passenger Traction	Car Door Restrictor not functioning
05-Jan	Passenger Traction	Car Door Restrictor not functioning
05-Jan	Type B Freight	Hydraulic system leaking excessively
06-Jan	LPPD Vert. Traction	Worn/Damaged Governor rope
06-Jan	Passenger Traction	Car Door Restrictor not functioning
06-Jan	Passenger Traction	Car Door Restrictor not functioning
07-Jan	Passenger Traction	Car Door Restrictor not functioning
08-Jan	Passenger Traction	Hoistropes require replacement(multiple strand breaks)
11-Jan	LPPD	Low Pressure switch not working/Emerg light and bell not working
12-Jan	LPPD Roped Hydro	Safeties do not work as required
12-Jan	Passenger Traction	Compensating ropes are badly worn/damaged
12-Jan	Passenger Traction	Faulty Governor Tension Sheave switch
13-Jan	LPPD Roped Hydro	Low Pressure switch not working
13-Jan	LPPD	Low Pressure switch not working
14-Jan	Passenger MRL	Car Door Restrictor not functioning
14-Jan	Passenger Traction	SOS switch not working/Missing fastner on Roller Guide
15-Jan	Passenger Traction	Governor Rope damaged/needs replacement
15-Jan	Passenger Traction	Machine Brakes maintance not completed/Overhead excessive
15-Jan	Passenger Traction	Door Restrictor/No Alaram Bell/No Phone/Past due Cat 1 and Brake testing
19-Jan	LPPD Vert. Encl	Low Pressure switch not functioning
19-Jan	LPPD Vert. Encl	Low Pressure switch not functioning/hallway door locks failing
20-Jan	Passenger Traction	Car Door Restrictor not functioning
21-Jan	Passenger Hydro	Car Door Restrictor not functioning
22-Jan	Passenger Traction	Car Door Restrictor not functioning
22-Jan	Passenger Traction	Car Door Restrictor not functioning
25-Jan	Passenger Traction	Compensating ropes are badly worn/damaged
25-Jan	Passenger Traction	Missing seals on adjustable components of overspeed governor
27-Jan	Passenger Traction	Missing seals on adjustable components of overspeed governor
27-Jan	LPPD Ram Traction	Car STOP switch and PIT Switch not working
28-Jan	Passenger Traction	Missing seals on adjustable components of overspeed governor and Emergency Brake (Rope Gripper)does not drop when required
28-Jan	Passenger Traction	Hoistropes require replacement(undersized and excessive rouging)
29-Jan	LPPD Ram Traction	Travelling cable dammaged due to misalinment between guiderail and car