

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale
07-Apr	LPPD Vert Encl	Car safties did not engage when tested
08-Apr	Passenger Hydro	Emergency Alarm Bell and Telephone not working
09-Apr	Passenger Traction	Missing Governor adjustment seal
09-Apr	LPPD Vert Encl	Emergency Alarm Bell not working
09-Apr	LPPD Vert Encl	Top hall station not code compliant - constant pressure
12-Apr	Passenger Traction	Counterweight Governor tension switch failed to operate
13-Apr	Passenger Traction	Governor Jaw would not drop when required to activate Car Safeties.
14-Apr	Passenger Traction	Breaks in Governor Rope
15-Apr	Passenger Traction	Car Door Restrictor/ Provide minimum running clearance from Counterweight to Hoistway Enclosure to comply with CSA B44-00 2.5.1.2.
15-Apr	Passenger Traction	Car Door Restrictor
20-Apr	LPPD Vert Encl	Low pressure switch not operational
20-Apr	LPPD Vert Encl	Hydraulic relief valve cartridge has had the tamperproof cover removed.
21-Apr	Passenger Hydro	Sync Ropes becoming slack when elevator is located at bottom landing
22-Apr	Passenger Traction	Both the telephone and alarm bell/button do not work
22-Apr	Passenger MRL	Hoisting belt monitoring system displaying faults.
23-Apr	Passenger Traction	Repair Car Door Restrictor/ Repair Car Governor Tension Switch.
23-Apr	Passenger Traction	Missing Seal on Overspeed Adjustment Setting on Overspeed Governor and Rope Gripper Pads worn through with a disabled wear switch.
26-Apr	LPPD Vert Encl	Lift Hall Door Lock won't open on Floor #2 to allow passengers to exit or enter Lift, and Holes in hoistway fascia present shear hard to passengers.
29-Apr	Passenger R Hydro	The safeties are rubbing the rail and wearing out the spring return hardware almost worn thru
29-Apr	Passenger Traction	Missing governor seals