## Elevator Shutdown Report

Date	Device Type	Rationale
		Counter Weight Runby No Good, to the point where it is breaking Schakle Springs
	LPPD Vert Encl	Failed Safety test
	LPPD Vert Encl	Stop switch in pit not working
	LPPD Vert Encl	Emergency Alarm Bell and lighting and stop switch not working
		Emergency Alarm bell and Phone not working (in car)
-	_	Car Door Restrictor not functioning
-		Car Door Restrictor not functioning
$\vdash$		Car Door Restrictor not functioning
		Car interior emergency exit accesss panel and surrounding
	Ü	ceiling system became detached during inservice inspection.
07-Nov	LPPD Vert Encl	Emergency Alarm Bell and lights not working
	LPPD Vert Encl	The in car stop switch/alarm button is broken
	MRL Traction	Car Door Restrictor not functioning/Broken hall door relating cable on 2 spd door
08-Nov	Passenger Hydro	Non-operating car door reopening device (safety edge)
	LPPD Vert Encl	No alarm/emergency lights /manual lowering is seized/ only one safety engages
09-Nov	Passenger Traction	Governor jaw failed to effect application of the safties.
		Car Door Restrictor not functioning
14-Nov	Passenger Traction	Car runs with Emergency escape hatch swith removed
17-Nov	Passenger Traction	Overspeed Seal missing on Car Governor.
18-Nov	Escalator	Anti reversal device not working on UP unit.
18-Nov	Passenger Hydro	Restrictor not functioning
21-Nov	LPPD Vert Encl	Alarm Bell not functioning with normal building power
		removed from control circuit unit.
21-Nov	LPPD Stair Pltfm	Uphill Ramp Switch not functioning with Platform in up position.
21-Nov	Passenger Hydro	Pressure switch not working
21-Nov	LPPD Vert Encl	Emergency Alarm Bell not working
21-Nov	Passenger Hydro	Non operating emergency alarm bell or in car telephone.
23-Nov	LPPD Vert Encl	Underpan is sitting on Pit Floor underneath unenclosed Platform Lift.
24-Nov	LPPD Vert Encl	Failed safety test. Elastic bands that hold the safety jaw in place are snapped off.
24-Nov	LPPD Vert Encl	Traction loss at the upper end of the shaft.
24-Nov	Passenger Traction	The hoist ropes have exceeded rejection criteria for being undersized
		with rouging present. This was called on the previous inspection (2 years ago).
		The low pressure switch doesn't change state mechanically.
-		The low pressure switch does not mechanically change state.
28-Nov	Passenger Traction	HVAC vent cover at top of hoistway missing - open access to hoistway
	LPPD Vert Encl	Low Pressure Switch not working
	Escalator	Cracked/split handrail.
30-Nov	Escalator	Brake was not holding at manufacturers specifications.