

Elevating Devices Shutdown Report Feb 2022

Date	Device Type	Rationale
01-Feb	Passenger Hydro	Repair Car Door Operation.(multiple issues)
02-Feb	Passenger Roped Hydro	Seal missing on Relief Valve (previously in 2019 and sealed in 2019 by AEDARSA). Escape Hatch Plug not attached to Hatch Door (Chain missing)
02-Feb	LULA Roped Hydro	Wire across F5 fuse holder
03-Feb	Passenger Traction	The hoist belt pulse monitoring device indicated a problem with one of the belts
04-Feb	Passenger Traction	Seals missing on the governor overspeed
07-Feb	Passenger Traction	Car door restrictor not working
07-Feb	Passenger Traction	The bottom directional limit and final limit are not mechanically actuating.
08-Feb	LPPD Vert Enclosed	Lift contacting Mast panels on way up and down and making loud noises. Screw column not lubricated and Lift is squeeling in travel.
09-Feb	Escalator	Large crack(s) in handrail
09-Feb	Escalator	Steps have knife edging /Cat 1 testing for 2021 not completed
09-Feb	Escalator	Steps have knife edging /Cat 1 testing for 2021 not completed
09-Feb	LPPD-Ball Screw	Emergency alarm bell does not work with the power off.
10-Feb	Passenger Traction	Car Door cladding has detached from Car Doors and is scrapping and in danger of falling off resulting in further equipment damage. Rope Gripper is not functioning properly and is intermittently starting up.
16-Feb	Passenger Traction	Emergency Alarm Bell and Phone do not work
16-Feb	Escalator	Broken drive chain switch will not actuate.
16-Feb	Escalator	Broken drive chain switch will not actuate.
16-Feb	Escalator	Broken drive chain switch will not actuate.
18-Feb	LPPD	Emergency phone in cab not working
22-Feb	LPPD	Seal cut on Relief Valve as well as Burnt wiring in Lift Controller.
22-Feb	Passenger Traction	Car door restrictor not working
22-Feb	Passenger Traction	Car door restrictor not working
23-Feb	Escalator	Large piece of step tread broken the leading edge of the step
23-Feb	Escalator	Both combplate safety switches at the top of the escalator fail to mechanically actuate. The complete teeth do not mesh with the step treads at the bottom of the escalator.
23-Feb	Escalator	A large piece of step tread is broken off of the leading edge of the step.
23-Feb	Passenger Traction	Car Governor Tension Switch is broken in pit.
23-Feb	Passenger Traction	Car door restrictor not working
23-Feb	Escalator	Step indexing test failed. Last three years of CAT 1 indexing not signed off. Brake operated switches are missing component preventing mechanical operation of the switch. The controller wiring for the switches is not as per the prints. Brakes not set/adjusted as per manufacturers specifications for torque or slide
23-Feb	Escalator	Step indexing test failed. Last three years of CAT 1 indexing not signed off. Reversal stop device is not working. Brakes not set/adjusted as per manufacturers specifications for torque or slide.
25-Feb	Passenger Traction	Missing Governor Overspeed Seal
25-Feb	Passenger Traction	Cinderblock haistway wall has become dislodged (top of hoistway)
28-Feb	Passenger Traction	Make necessary Repairs to Car Door Clutch.