

AEDARSA Shutdown List - 2020

Date	Device Type	Rationale		
02-Jun	LULA	Low pressure switch not working		
02-Jun	Passenger Traction	Emergency light/alarm and phone not operating		
02-Jun	Passenger Traction	Car Door Restrictor not working		
02-Jun	Passenger Traction	Car Door Restrictor not working		
02-Jun	Passenger Traction	Car Door Restrictor not working		
04-Jun	Passenger Traction	Brake failure/issue repairs required		
04-Jun	Passenger Traction	Governor rope prevents safeties applying.		
05-Jun	Passenger Hydraulic	Emergency light/alarm and phone not operating		
05-Jun	Passenger Traction	FEO does not function (Phase 2)		
08-Jun	Passenger Hydraulic	Car door restrictor not working		
09-Jun	Passenger Traction	Missing governor seal		
09-Jun	Passenger Traction	Car door restrictor not working		
09-Jun	Passenger Traction	Car door restrictor not working & Comp sheave switch failure		
09-Jun	Passenger Traction	Rope Gripper failed to apply when required		
09-Jun	Passenger Traction	Rope Gripper pads worn (excessivley)		
10-Jun	Passenger Hydraulic	Car Door Restrictor failed		
11-Jun	Passenger Traction	Car Emergency and Alarm Bell not working		
11-Jun	Passenger Hydraulic	Low pressure switch not working		
12-Jun	Passenger Traction	Rope Gripper failed to stop elevator/Pull Through seal missing		
13-Jun	Escalator	Broken drive chain device and reversal stop device not working		
15-Jun	Passenger Traction	Car Door Restrictor not working		
15-Jun	Escalator	Reversal stop device not working		
15-Jun	Escalator	Broken drive chain device/switch not working		
16-Jun	Passenger Traction	Car door restrictor not working and Governor Overspeed seal is missing		
16-Jun	Passenger Traction	Single Bottom Cylinder Repalcement ORDER expired		
16-Jun	Passenger Traction	Car door restrictor not working		
17-Jun	Escalator	Reversal stop device not working		
19-Jun	LPPD Stair Pltfm	Safety Switch(up direction) failed		
19-Jun	Passenger Traction	Car door restrictor not working		
22-Jun	Passenger Hydraulic	Low pressure switch not working		
23-Jun	LPPD Stair Pltfm	Lift gets stuck between floor intermittently		
25-Jun	Passenger Traction	Rope Gripper failed to apply when required		
25-Jun	Passenger Traction	Car Door Restrictor failed		
25-Jun	Passenger Traction	Missing governor seal		
26-Jun	LPPD Roped Hydro	Low pressure switch not working		
30-Jun	Passenger Hydraulic	Low pressure switch not working		
30-Jun	Passenger Hydraulic	Car door restrictor not working		