

### AEDARSA Shutdown List - 2020

Date	Device Type	Rationale
04-Aug	Escalator	Reversal stop device not a manual reset switch
04-Aug	Escalator	Reversal stop device not a manual reset switch
04-Aug	Escalator	Reversal stop device not a manual reset switch
04-Aug	Escalator	Reversal stop device not a manual reset switch
04-Aug	Escalator	Reversal stop device not a manual reset switch
04-Aug	Escalator	Reversal stop device not a manual reset switch
05-Aug	Passenger Hydraulic	Car Door Restrictor failed
05-Aug	Passenger Traction	Car Door Restrictor failed
06-Aug	Passenger Hydraulic	Car emergency phone and Bell not working
07-Aug	LPPD Stair Platform	Carriage SOS and Slack Rope Switches failed to operate
07-Aug	Passenger Traction	Missing seal on governor overspeed
10-Aug	Escalator	Damaged handrail
11-Aug	Passenger Traction	Car Door Restrictor failed
12-Aug	Passenger Traction	Missing seal on governor overspeed
12-Aug	LPPD Ram	Device brakes traction
13-Aug	Passenger Traction	Missing seal on governor overspeed
13-Aug	Passenger Hydraulic	Car emergency phone and Bell not working
13-Aug	Passenger Traction	Car Door Restrictor failed
17-Aug	Passenger Traction	Emergency Brake(Rope Gripper) failed
17-Aug	Passenger Hydraulic	Car Door Restrictor failed
17-Aug	Passenger Traction	Gov pull through spring seal missing/escape hatch switch failed
17-Aug	Escalator	Severely cracked handrail
17-Aug	Escalator	Severely cracked handrail
18-Aug	Escalator	Damaged handrail
18-Aug	Passenger Traction	Missing seal on governor overspeed
18-Aug	Hydraulic Freight	Upper hall door interlock was jumped out
19-Aug	Escalator	Skirt index values exceed values allowed by code/skirt switch failed
19-Aug	Escalator	Skirt index values exceed values allowed by code
19-Aug	LPPD Ram	Safeties failed to apply
19-Aug	Passenger Traction	Car Door Restrictor failed
19-Aug	Passenger Traction	Car Door Restrictor failed
19-Aug	LPPD Vert Enclosed	Device runs with hall door (upper) Unlocked
20-Aug	Passenger Traction	Car Door Restrictor failed
20-Aug	LPPD Roped Hydro	Safeties failed to apply
21-Aug	Passenger Traction	Emergency Brake missing parts/loose holding pin
24-Aug	LPPD Roped Hydro	Safeties failed to apply and Low-Pressure switch failed
25-Aug	Manlift	Car Safeties expired(March2020) replacement/recert required
25-Aug	LPPD Vert Enclosed	Safety gear broke off during drop test
26-Aug	Passenger Traction	Missing seal on governor overspeed
27-Aug	LPPD Roped Hydro	Low pressure switch failed
27-Aug	LPPD Roped Hydro	SOS and Slack chain switches failed
28-Aug	Passenger Traction	Car Door Restrictor failed