

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale	
02-Oct	LPPD	Door gate/interlock failed	
04-Oct	Passenger Traction	Comp Rope meet rejection criteria for replacement	
04-Oct	Passenger Traction	Comp Rope meet rejection criteria for replacement	
04-Oct	Passenger Traction	Comp Rope meet rejection criteria for replacement	
04-Oct	Passenger Traction	Comp Rope meet rejection criteria for replacement	
04-Oct	Passenger Traction	Hoist and Comp Rope meet rejection criteria for replacement	
04-Oct	Passenger Traction	Hoist Rope meet rejection criteria for replacement	
05-Oct	Dumbwaiter	Devcie operates with bottom landing door open	
07-Oct	LPPD	Alarm bell not working	
08-Oct	LPPD	Non-compliance to the SCA- permit/inspections	
08-Oct	LPPD Ver Encl Trac	Safeties failed to engage during drop test.	
14-Oct	LPPD	Ropes did not break traction while car on safeties	
14-Oct	Passenger Hydro	The car door restrictor failed	
15-Oct	LPPD Ver Encl Trac	Safeties failed to engage during drop test.	
20-Oct	LPPD Ver Encl Trac	Lower landing hall door lock not operational	
20-Oct	LPPD Ver Encl Trac	Illegal Alteration to hall door created safety hazard	
21-Oct	LPPD Ver Encl Trac	Safeties failed to engage during drop test.	
22-Oct	Passenger Hydraulic	Car Door Restrictor	
22-Oct	Passenger Traction	Car Door Restrictor and Hoist Ropes	
29-Oct	LULA	Car door detector and low pressure switch not working	