

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale	
01-Dec	LPPD Roped Hydro	Low Pressure switch not working	
01-Dec	Passenger Hydro	Emergency phone and Alarm bell not functioning	
01-Dec	LPPD Vert Enclosed	Final limit and Hall Door contact not working	
02-Dec	LPPD Traction	Loose bolts on cables to the frame fastening	
07-Dec	Passenger Traction	Counterweight pit buffer switch damaged and not working	
08-Dec	Passenger Traction	Shackle lacing has cut through rope shackles	
08-Dec	Passenger Traction	Failed governor spin test	
10-Dec	Passenger Traction	Hoist rope replacement and Car Door Detector failed	
14-Dec	LPPD Vert Enclosed	Auto fold ramp is severely damaged	
17-Dec	LPPD Vert Enclosed	Emergency Alarm bell not working	
18-Dec	Passenger Traction	Car Door Restrictor not functioning	
21-Dec	Passenger Traction	Machine Brake holding pin dislodged	
21-Dec	Vert Encl Rope Hydr	Remove from service at Owner request	
21-Dec	Vert Encl Rope Hydr	Remove from service at Owner request	
21-Dec	Vert Encl Rope Hydr	Remove from service at Owner request	
21-Dec	Vert Encl Rope Hydr	Owner failed to complete repairs and overdue for inspections	