

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale
03-Nov	Passenger Traction	Counterweight governor overspeed switch failed
04-Nov	Escalator	Handrail damage/hazard
04-Nov	Passenger Traction	Missing "key" on output shaft on motor/gearbox
05-Nov	Passenger Traction	The car door restrictor failed
09-Nov	Escalator	Excessive brake slide
13-Nov	Escalator	Damaged(severley) handrail
13-Nov	Escalator	Handrail damage/hazard
16-Nov	LPPD Roped Hydro	Low Pressure switch not working
17-Nov	Passenger Traction	Hoistropes meet rejection criteria
17-Nov	Passenger Traction	Hoistropes meet rejection criteria
17-Nov	Passenger Traction	Misseng seal on car governor
17-Nov	LPPD Roped Hydro	Safeties failed to engage
23-Nov	Escalator	Failed SSPI testing and Comb Impact test
23-Nov	Escalator	Failed SSPI testing
24-Nov	Roped Hydro	Door Restrictor/Hoist rope shackle/Low pressure switch
25-Nov	Passenger Hydro	The car door restrictor failed
25-Nov	Passenger Traction	Phone and Alarm Bell not working
26-Nov	LPPD	Slack Chain switch failed
26-Nov	Passenger Hydro	Phone and Alarm Bell not working
27-Nov	Passenger Hydro	Phone and Alarm Bell not working
27-Nov	LPPD stair Chair	Stop switch not working