

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale		
02-Sep	Passenger Traction	Hoistropes require replacement (damage)		
02-Sep	Manlift	Slack governor rope		
02-Sep	Passenger Traction	Hoistropes require replacement (damage)		
03-Sep	Passenger Traction	Car Door Restrictor/Governor Rope rubbing on guard		
03-Sep	Passenger Traction	Car Door Restrictor		
04-Sep	Lppd Vert Enc	Safties did not engage properly		
04-Sep	Passenger Traction	Car emergency phone and Bell not working		
04-Sep	Vert Encl- Ram	Car Safeties not engaging/Alarm bell		
04-Sep	Roped Hydro	Car emergency phone and Bell not working		
04-Sep	Roped Hydro	Car emergency phone and Bell not working		
08-Sep	Escalator	Damaged handrail		
09-Sep	Pass Traction MRL	Car gate switches failed		
10-Sep	Passenger Hydro	Car emergency phone and Bell not working		
10-Sep	Manlift	Governor Rope not attached/SOS failed/Disconnect switch(car top) full of water		
11-Sep	Passenger Traction	Car emergency phone and Bell not working		
14-Sep	Lppd Vert Enc	Carriage stop switch does not work		
14-Sep	Passenger Hydro	Car Door Restrictor		
15-Sep	Passenger Traction	Car Door Restrictor		
15-Sep	Passenger Traction	Car Door Restrictor		
16-Sep	LPPD RAM	Drive pulley falling off		
16-Sep	Passenger Traction	Car Door Restrictor		
18-Sep	Passenger Hydro	Car Emergency phone/Cat 1 tests not done		
18-Sep	Passenger Traction	Car Door Restrictor		
23-Sep	Passenger Traction	Governor Seal missing		
24-Sep	Passenger Traction	Car emergency phone and Bell not working		
26-Sep	Passenger Traction	Comp Rope met rejection criteria for replacement		
28-Sep	LPPD Traction	Governor overspeed switch failed to operate		
29-Sep	LPPD Roped Hydro	Car safties failed to apply		
30-Sep	LPPD Roped Hydro	Low Pressure Switch failed		
30-Sep	LPPD Roped Hydro	Car safties failed to apply		