

AEDARSA Shutdown List - 2021

| Date | Device Type | Rationale |
|--------|---------------------|---|
| 01-Feb | Passenger Traction | Governor overspeed adjustment seal missing |
| 03-Feb | Passenger Traction | Missing fitting (S hooks) on comp chain |
| 04-Feb | MRL | Emergency phone and Bell not working |
| 05-Feb | Passenger Traction | Worn(excessively) roller guide under car platform |
| 05-Feb | Vert Traction RAM | Car safeties would not apply/function |
| 05-Feb | Passenger Traction | Damaged(excessive) compensating ropes |
| 08-Feb | Passenger Traction | Elastomeric Hoisting Means(belts) worn |
| 09-Feb | LPPD | Low Pressure switch not working. |
| 10-Feb | LPPD Vert. Traction | Car governor rope/Top floor hall door lock/Pit switch/ Car governor tension switch needs replacement/not working |
| 10-Feb | Passenger Traction | Governor overspeed adjustment seal missing |
| 10-Feb | Passenger Traction | Car door restrictor not functioning |
| 10-Feb | LPPD | Low Pressure switch not working. |
| 10-Feb | LPPD | Low Pressure switch not working. |
| 10-Feb | LPPD | Emergency light and bell not working |
| 11-Feb | Passenger Hydro | Emergency light and alarm not working |
| 16-Feb | Passenger Traction | Car door restrictor not functioning |
| 18-Feb | Passenger Traction | SOS Switch not functioning |
| 18-Feb | Passenger Traction | Car Door restrictor not functioning/CWT Spring Buffer (corroded) |
| 18-Feb | LPPD Traction RAM | Safeties failed to apply |
| 19-Feb | LPPD Roped Hydro | Low Pressure switch not working. |
| 22-Feb | Passenger Traction | Damaged/Broken safety gear |
| 23-Feb | Escalator | Skirt switch/Excessive loaded gap/Cat 1 test past due |
| 24-Feb | Escalator | Damaged/missing step treads |
| 25-Feb | Passenger Traction | Car Door Restrictor not functioning |
| 25-Feb | Escalator | Combplate impact switch/Handrail tension belt issue |