

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale
01-Mar	Passenger Traction	Car Door Restrictor not functioning
01-Mar	Escalator	Reversal stop switch not working (mechanically)
01-Mar	Escalator	Oil on brake drum/pads/Damaged step treads
01-Mar	Passenger Hydro	Low Pressure Switch failed to operate
02-Mar	Escalator	Main drive shaft break failed to hold
02-Mar	Escalator	Main drive shaft break failed to hold
03-Mar	Passenger Traction	Compensation Ropes require replacement
03-Mar	Passenger Traction	Car Door Restrictor not functioning
03-Mar	Passenger Hydro	Car Door Restrictor/Emergency Exit/Excessive Sill to Hoistway gap
03-Mar	Escalator	Combplate impact switch not functioning
03-Mar	Escalator	Oil on brake drum/pads/Damaged handrail
04-Mar	Escalator	Brake TQ not to spec/skirt switch failed to operate
08-Mar	Passenger Traction	Missing seal on governor/Car Door Restrictor not functioning
09-Mar	LPPD Vert Encl.	Slack chain switch failed to operate
09-Mar	Passenger Traction	Hoist ropes undersized with excessive rouge
10-Mar	Passenger Traction	Car Door Restrictor not functioning
10-Mar	Escalator	Handrail inlet switch not working
10-Mar	Escalator	Damaged step roller(s)
12-Mar	LPPD Vert Encl.	Multiple safety switches bypassed
15-Mar	Escalator(s)	SSPI test failed to meet code requirements (4 devices)
17-Mar	LPPD Vert Encl.	Emergency Alarm Bell not functioning.
18-Mar	LPPD Vert Encl.	Emergency Alarm Bell not functioning.
19-Mar	LPPD Vert Encl.	Car Safeties failed to apply during test
19-Mar	Escalator	Failed SSPI -loaded gap exceeds 5mm
19-Mar	Escalator	Failed SSPI -loaded gap exceeds 5mm
22-Mar	Escalator	Damaged Step treads/Reversal stop device failed to operate
22-Mar	Escalator	Damaged Step treads/Reversal stop device failed to operate
22-Mar	LPPD Vert Encl.	Excessive corrosion of pit equipment/Cylinder/Hitch plate
23-Mar	LPPD Vert Encl.	Mechanical Safeties not functioning
23-Mar	Passenger Hydro	Car gate switch not functioning
25-Mar	Passenger Hydro	Excessive hydraulic leak
26-Mar	Escalator	Broken Combplates/missing Cat 1 and procedures for RVSW and Handrail Force
26-Mar	Escalator	Broken Combplates/missing Cat 1 and procedures for RVSW and Handrail Force
26-Mar	LPPD Vert Encl.	Safeties did not apply when tested
26-Mar	Passenger Hydro	Car Door Restrictor/Emerg Alarm and phone not working
29-Mar	Passenger Traction	Car Door Restrictor not functioning
29-Mar	LPPD Stair Platform	Lift operates (empty)with the platform in folded down position
30-Mar	Passenger Traction	Car Levelling exceeds code requirements (on all floors)

AEDARSA Shutdown List - 2021

3
3