

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale
03-Aug	Escalator	Broken stpe treads / Reversal stopping device
03-Aug	Escalator	Broken stpe treads
04-Aug	LPPD- Vert Enclcd	Lift operates with main disconnect in OFF position
05-Aug	Passenger Traction	Emergency Phone and Alarm Bell/ Missing Governor Seal
05-Aug	LPPD Roped Hydro	The low pressure switch does not mechanically change state.
10-Aug	LPPD Vert Enclosed	Changes made to controller wiring, bypassed safety circuit
11-Aug	Passenger Traction	In car telephone and emergency alarm bell are not working.
11-Aug	Passenger Traction	In car telephone not working.
12-Aug	Manlift Endless Belt	Belt is breaking down and is torn in multiple locations
18-Aug	LPPD Vert Enclosed	Car Cam will not operate to engage Hall Door Lock Cam to open Hall Doors at landing to allow passengers to enter or exit Lift.
18-Aug	LPPD Vert Enclosed	Emergency Alarm does not operate with normal building power removed from control circuit.
20-Aug	Manlift/Alimak	Emergency Brake Safeties past expiration date
23-Aug	LPPD Stair Platform	Directional Switch on Auto Fold Ramp does not stop Lift when traveling in the Up direction.
24-Aug	LPPD Vert Enclosed	Repair low pressure switch. Car and Hall Calls were replaced with set/reset buttons and are not constant pressure.
24-Aug	LPPD Roped Hydro	Car safeties not engaging.
25-Aug	Escalator	The left step wheel track was broken in multiple areas and required to be changed out. The right step wheel track was cracked and required repairs.
25-Aug	LPPD Stair Chair	Emergency Stop Button and alarm not working. Chair control switch broken off.
25-Aug	LPPD Roped Hydro	During the inspection the lift would begin running in the up direction for the full rise without demand being placed and would occasionally run in the up direction when down demand was place.
25-Aug	LPPD Roped Hydro	The safety gear did not engage and stop the carriage during two consecutive drop tests.
25-Aug	LPPD Roped Hydro	The safeties failed to mechanically engage during a drop test.
25-Aug	LPPD Vert Enclosed	The device breaks traction.
25-Aug	Type B Freight	The pit stop switch doesn't work.
25-Aug	LPPD Roped Hydro	The low pressure switch does not mechanically change state.
25-Aug	Escalator	Anti reversal did not function as required.
25-Aug	Escalator	Excessive cracks in escalator handrail.
26-Aug	LPPD Vert Enclosed	Lift runs with Hall Door Lock in unlocked position.
26-Aug	LPPD Vert Enclosed	Emergency Alarm Bell does not work when normal building power has been removed from control circuit.
26-Aug	Escalator	The Right side skirt switches were not functioning.
26-Aug	Escalator	The Right side skirt switches were not functioning.
26-Aug	Escalator	The Right side skirt switches were not functioning.
26-Aug	LPPD Roped Hydro	The low pressure switch does not mechanically change state.
30-Aug	LPPD ballscrew unenclosed	The underpab switches are not functioning on the side oposite of the ramp.
31-Aug	LPPD	Manual hand cranking assembly not engaging the drive unit
31-Aug	LPPD Roped Hydro	The safeties failed to hold the car/platform.(tested 3x)
31-Aug	LPPD	Slack rope switch not working