

AEDARSA Shutdown List - 2021

Date	Device Type	Rationale
02-Sep	Passenger Hydro	Car door restrictor not functioning
02-Sep	LPPD Roped Hydro	Car safeties would not engage during the drop test.
07-Sep	Passenger Traction	Car door restrictor not functioning
10-Sep	Passenger Hydro	Telephone and emergency alarm bell do not work.
13-Sep	Passenger Hydro	Non operational Low Pressure Switch.
17-Sep	Freight Traction	No Category One testing completed in 2020.
17-Sep	LPPD Roped Hydro	Car Safeties did not engage during Safety Drop Test.
21-Sep	LPPD Roped Hydro	The Emergency Light and Alarm bell are not functioning
21-Sep	LPPD Vert Encl	The Emergency Light and Alarm bell are not functioning
21-Sep	LPPD Vert Encl	SOS switch was not functioning
22-Sep	LPPD Vert Encl	Emergency Alarm Bell not functioning.
		Counterweight contacting back of hoistway wall
		Floor 2 Hall Door Locked Contacts not functioning on Lift.
22-Sep	Passenger Traction	The governor jaw seal for pull on/pull through had been removed and replaced
23-Sep	LPPD Vert Encl	Car Safeties failed to apply on two consecutive Safety Drop Tests
		Rope Clips for Hoist Ropes are missing above Rope Shackles on Car side.
27-Sep	Passenger Traction	Car door restrictor not functioning
27-Sep	Passenger Traction	Telephone and emergency alarm bell do not work.
27-Sep	Passenger Traction	Car door restrictor not functioning
		Compensation sheave switch (pit) out of adjustment
28-Sep	Passenger Traction	Missing Door restrictor brackets (floors L and B)
		Provide clearance between Car Governor Rope and Governor Tension Sheave Guard.
29-Sep	Passenger Traction	No Maintenance Provider