

## Information Bulletin No. IBE20-008 ISSUED Jan 31, 2020

**Subject: Failure to Comply with Cited Inspection Deficiencies** 

**Notice:** All Owners and Elevating Device Service Providers (EDSP)

As a result of AEDARSA's internal audit of their inspection services and in consultation with Alberta Municipal Affairs it is noted that many deficiencies as set out in AEDARSA's inspections are not being completed at all or by the completion date.

Failure to comply with an issued deficiency by an authorized Safety Codes Officer is a violation under the *Safety Codes Act* in Alberta. The noncompliance of an issued safety directive is unacceptable and can result in injuries or death of persons using an elevating device.

Therefore, this notice is to inform you that ALL AGENCIES will be issuing "Orders" for the removal of all elevating devices that have not completed the remedial repairs by the date specified in an inspection report issued by a Safety Codes Officer. This order will be served on BOTH the OWNER and EDSP

The owner or the EDSP is responsible to maintain their elevator in compliance with the *Elevating Devices Codes Regulation* and in a fashion that precludes the need for an SCO to cite violations. In addition, if a deficiency is cited it will be completed in a timely manner.

## **Effective Date of Notice:**

This policy becomes effective immediately

McKernon, VP Operations, AEDARSA