

ELEVATOR SHUTDOWN REPORT

Date	Coding	Devic	Rationale
01-May	EM027	PH	Relief Valve not sealed
01-May		PT	Governor Overspeed seal missing/temporary seal on PO/PT tension spring
04-May	EM027	PH	Missing seal on Relief Valve
05-May	EC027	PH	The car door restrictor doesn't work.
08-May	XA027	ESC	Escalator runs with the combplate teeth not meshed with the step treads
08-May	XA003	ESC	breakaway torque significantly higher than the OEM maximum and the stopping distance is shorter than the OEM minimum.
	CA200		There is a lateral crack present in the escalator step track.
10-May	HL020	BF	Drive Sheave failure, Loss of Traction
	HL053		
12-May	EH012	PT	The bottom final limit is broken off its bracket and can not be actuated by the elevator cam.
15-May	HL036	BF	Repair Emergency Alarm Bell inside Lift.
16-May	EC076	MRL	Car Door Restrictor
16-May		PT	No tension on governor rope
16-May	HL020	BF	Unit was breaking traction/stopping in the up direction some load in the car.
18-May	EC019	FH	No alarm bell or phone without a/c power
	EC002		
18-May	EC019	PT	Alarm bell and telephone do not fuction when power removed
	EC002		
29-May	XA003	ESC	The broken/sagging step device can be reset and will run while in the tripped position.
	CA200		The brake is over maximum torque and under minimum stopping distance.
29-May	EC019	PT	The telephone and alarm bell both do no function.
	EC002		The car door strikes junction boxes inside the hoistway when run on access operation.
	EH074		The sump piping has been located directly below the governor tension.
	EH029		tension sheave /weights, blocking it from falling
	EM058		The elevator can run with the overspeed actuating device in the tripped position.
31-May	HL013	BF	Lift stopping between floors causing passenger entrapments.
31-May	EM063	PT	Rope brake installed incorrect. Operation is incorrect as well
31-May	EC002	Lula	Emergency Alarm bell not working when 110v power removed
	EC019		Emergency Phone not working when 110v power removed

Coding	Count
EC011	3
EC019	3
CA200	2
XA003	2
EC002	2
EM027	2
HL020	2
EH029	1
EC027	1
HL013	1
EM063	1
EH074	1
EH012	1
EM058	1
HL036	1
XA027	1
EC076	1
HL053	1
(blank)	
<b>Grand Total</b>	<b>27</b>