

Date	Device	Rationale
02-Aug-23	Passenger Traction	Emergency Phone and Alarm Bell Not Working
03-Aug-23	Passenger Traction	Overspeed Governor Adjusted and not Re-sealed properly
08-Aug-23	Barrier-Free	Device breaks traction, can move the lift by hand two feet above the bottom floor. Also does not travel down from the top floor with an empty car.
10-Aug-23	Passenger Hydraulic	Car Door Restrictor Failure
10-Aug-23	Barrier Free	The emergency stop switch inside the lift does not mechanically function.
11-Aug-23	Barrier Free	The mechanical portion of the safety linkage does not stop the device when a drop test was preformed
11-Aug-23	Passenger Hydraulic	Low Pressure Switch Failure
15-Aug-23	Passenger Hydraulic	Traveling up to the top floor the whole elevator cab shifts to one side. And it does the same thing leaving the top floor. Pistons are out of sync
15-Aug-23	Manlift	Hall door bottom and top floor will open when car not at landing
16-Aug-23	Passenger Traction	Car Governor overspeed Seal missing.
15-Aug-23	LULA	Non operating 2 way communication with no alarm bell
16-Aug-23	Barrier-Free	The safeties failed to engage the rail and stop the car on two separate drop tests.
17-Aug-23	Passenger Hydraulic Barrier-Free Enclosed	The car door restrictor doesn't work on the front door.
17-Aug-23	Vertical	Failure of Alarm and Communication devices
22-Aug-23	Passenger Hydraulic	Low Pressure Switch Failure
22-Aug-23	Barrier-Free	The Mechanical Safeties failed to stop the lift when the no-load Safety test test was performed.
23-Aug-23	Passenger Hydraulic	Car Door Restrictor Failure
23-Aug-23	Barrier-Free	Failure of the Sensitive Surface Device/Pan under the lift platform (Unenclosed Vertical Platform)
23-Aug-23	Passenger Hydraulic	Car Door Restrictor Failure
23-Aug-23	Passenger Hydraulic	Car Door Restrictor Failure
23-Aug-23	Escalator	Skirt Switch Failure
24-Aug-23	Barrier-Free	Repair Emergency Alarm Bell
24-Aug-23	Barrier-Free	Low Pressure Switch Failure The controller cabinet is bent/damaged to the point that once the cover was removed it could not be reinstalled in such a way that it would not be struck by the moving lift.
25-Aug-23	Barrier-Free	The safeties did not mechanically engage and stop the car during 2 separate drop tests.
25-Aug-23	Barrier-Free	The in car emergency stop button does not work
15-Aug-23	Passenger Hydraulic	2 feet of water in the elevator pit
28-Aug-23	Passenger Hydraulic	Emergency Communications Failure
29-Aug-23	Passenger Traction	Emergency Communication Failure
30-Aug-23	Passenger Hydraulic	Car Door Restrictor Failure
30-Aug-23	Passenger Traction	Emergency Brake Failure Counterweight Sheave Bearing Failure
31-Aug-23	Passenger Traction	Car Door Restrictor Failure
31-Aug-23	Passenger Traction	Elevator Runs with Safety Operated Switch Open Elevator Runs with Emergency Exit Switch Open Elevator Runs with Car Governor Overspeed Switch Open
31-Aug-23	Passenger Traction	Car Door Restrictor Failure
31-Aug-23	Passenger Traction	Car Door Restrictor Failure