

AEDARSA Shutdown List

Date	Device Type	Rationale
03-Jul	Passenger traction	Car emergency phone and Bell not working
03-Jul	Passenger Traction	Missing Governor Seal
06-Jul	LULA	Low Pressure switch not working
06-Jul	Escalator	Multiple Broken/Missing step treads
07-Jul	Passenger Traction	Alarm bell not working/Broken
07-Jul	Passenger Hydro	Missing Seal on pressure relief(2 insp. Cycles)
07-Jul	Traction MRL	Car Door Restictor failed/Crossed Hoistropes
07-Jul	LPPD-Roped Hydro	Low Pressure switch not working (electricaly)
07-Jul	Passenger Roped Hydr	Car Door Restrictor failed
07-Jul	Passenger Hydro	Car emergency phone and Bell not working
08_Jul	Roped Hydro	Car Door Restrictor failed
09-Jul	Passenger Hydro	Car emergency phone and Bell not working
10-Jul	Passenger Traction	Hoist Ropes replament ORDER expired
13-Jul	Type B Freight Plfm	Top landing interlock failure
13-Jul	Traction MRL	Car emergency phone and Bell not working
13-Jul	LPPD-Vert Enclosed	Loss of traction due to worn drive sheave
14-Jul	LPPD Roped Hydro	Missing Relief Valve Seal
15-Jul	Passenger Traction	Rope Gripper pinned open
17-Jul	Manlift	Top floor ENTRANCE gate missing
20-Jul	LPPD Vert Encl roped H	Low Pressure switch not working
20-Jul	Passenger Traction	Car Door Restrictor failed
21-Jul	Escalator	Loaded gap exceeds 5mm
21-Jul	Escalator	Loaded gap exceeds 5mm
22-Jul	Passenger Traction	Missing Seal on Overspeed Governor
23-Jul	Passenger Hydro	Car emergency phone and Bell not working
23-Jul	Escalator	Severley damaged handrail
24-Jul	Passenger traction	Car Emergency phone not working
27-Jul	LPPD- Traction	Top landing hall door OPEN switch failed
27-Jul	Manlift	No 2way com/alarm and hazardous condition above lift
27-Jul	Roped Hydro	Car went onto safeties due to poor oil condition
27-Jul	Passenger Hydro	Low Pressure switch failure/Missing Overspeed valve seal
29-Jul	Passenger Traction	Suspension Means Monitoring device FAULT
30-Jul	Passenger Traction	Hoistropes replacement required